

Docket No.: 246472003920  
(PATENT)

**IN THE UNITED STATES PATENT AND TRADEMARK OFFICE**

\_\_\_\_\_  
In re Letters Patent of:  
Helmut D. LINK et al.

Confirmation No.: 5128

Patent No.: 7,527,629

Issued: May 5, 2009

For: INSTRUMENT SET FOR FITTING AN  
\_\_\_\_\_  
INTERVERTEBRAL JOINT PROSTHESIS

**REQUEST FOR CERTIFICATE OF CORRECTION  
PURSUANT TO 37 CFR 1.322**

Attention: Certificate of Correction Branch  
Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Sir:

Upon reviewing the above-identified patent, Patentees noted typographical errors which should be corrected.

On the Front Page:

Under Section (30), "Foreign Application Priority Data," please replace "02005629" with ---02005629.7---.

In the Specification:

Column 1, line 8, please replace "European Application No. 02 005 628.7" with ---European Application No. 02 005 629.7---.

Column 4, line 36, please replace "1800" with ---180°---.

Some of the errors were found in the application as filed by applicant. Please charge our Deposit Account No. 03-1952 in the amount of \$100.00 covering the fee set forth in 37 CFR 1.20(a).

The errors now sought to be corrected are inadvertent typographical errors the correction of which does not involve new matter or require reexamination.

Transmitted herewith is a proposed Certificate of Correction effecting such amendment. Patentees respectfully solicit the granting of the requested Certificate of Correction.

The Director is hereby authorized to charge any deficiency in the fees filed, asserted to be filed or which should have been filed herewith (or with any paper hereafter filed in this application by this firm) to our Deposit Account No. 03-1952, under Order No. **246472003920**.

Dated: August 5, 2009

Respectfully submitted,

By Bradley J. Meier  
Bradley J. Meier

Registration No.: 44,236  
MORRISON & FOERSTER LLP  
1650 Tysons Blvd, Suite 400  
McLean, Virginia 22102  
(703) 760-7743

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION**

Page 1 of 1

PATENT NO. : 7,527,629  
APPLICATION NO. : 10/731,432  
ISSUE DATE : May 5, 2009  
INVENTOR(S) : Helmut D. LINK et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the Front Page:

Under Section (30), "Foreign Application Priority Data," please replace  
"02005629" with ---02005629.7---.

In the Specification:

Column 1, line 8, please replace "European Application No. 02 005 628.7"  
with ---European Application No. 02 005 629.7---.

Column 4, line 36, please replace "1800" with ---180°---.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Bradley J. Meier  
MORRISON & FOERSTER LLP  
1650 Tysons Blvd, Suite 400  
McLean, Virginia 22102

1

va-278747